ELECTRATEST – GENERIC RISK ASSESSMENT - PART B OFFICE PREMISES

1. VISITING CLIENTS PREMISES	
HAZARDS	PRECAUTIONS / PROCEDURES
Clients:	Fill in the visitors book at reception
Work activities/processesLocation	Comply with the clients procedures /rules for contractors:
	 Site induction Access and egress requirements Fire and evacuation

Personal protective equipmentProhibited areas

2. PORTABLE APPLIANCE TESTING	
HAZARDS	PRECAUTIONS / PROCEDURES
Contact with live cables/surfaces	All electrical work must be carried out by trained and competent person
Electrocution	
Electric shock	Follow written electrical test procedures
Burns	
➤ Fire	Use correct testing equipment
Property damage	
Equipment damage	Isolate and disconnect from mains

ELECTRATEST – GENERIC RISK ASSESSMENT - PART B OFFICE PREMISES

4. LIGHTING	
HAZARD	PRECAUTIONS / PROCEDURES
Low levels of lighting Slips, trips and falls (resulting in serious injury)	No work is to be carried out without adequate lighting: Ensure that the lighting levels are adequate to enable the inspection and test to be carried out safely
	Where necessary obtain and use 110v portable task lighting

6. HAZARDOUS SUBSTANCES /MATERIALS		
HAZARDS	PRECAUTIONS / PROCEDURES	
Exposure to toxic, harmful, irritant or	Comply with the clients procedures	
corrosive substances causing acute and/or chronic ill health	/rules for contractors	
	Adhere to information, mandatory	
Fire and/explosion	and/or warning signs	
	Keep out of all hazardous areas	

ELECTRATEST – GENERIC RISK ASSESSMENT - PART B OFFICE PREMISES

9. CONFINED SPACE/AREA	
HAZARDS	PRECAUTIONS / PROCEDURES
Excess and/or lack of oxygen Toxic gases /vapours Fire and/explosion Engulfment Slips trips and falls	Avoid entry wherever possible. Do not enter a confined space unless trained to do and then: Comply with the clients procedures /rules for contractors Devise a safe system of work Comply with permit-to-work procedures where applicable You intrinsically safe equipment when required and available Adhere to information, mandatory and/or warning signs

10. MANUAL HANDLING	
HAZARDS	PRECAUTIONS / PROCEDURES
Muscular skeletal disorders Strains/pulled muscles and ligaments Back injuries Cuts and bruises	Avoid, assess, reduce Avoid, use mechanical means if at all possible Assess, the weight, reduce into smaller packages/loads Decide if one or two persons are required for the lift Use kinetic handling techniques Where the correct personal protective equipment